single storey extension between garden room and existing kitchen outrigger and associated alterations. Cut Thorn Farm Macclesfield Forest

Proposed change in design to extant garden room addition and additional linking

**Granted Conditionally** 

Condition/s Fully Discharged

Condition/s Not Discharged

Condition/s Not Discharged

Condition/s Partly Discharged

Condition/s Partly

Condition/s Partly Discharged

Condition/s Fully Discharged

Condition/s Fully Discharged

Condition/s Partly Discharged

Condition/s Fully Discharged

Condition/s Partly Discharged

Condition/s Partly Discharged

Discharged

Refused

Applications determined by the Head of Planning between 01/10/2023 and 31/10/2023

We have taken reasonable steps to ensure the information provided by us on this website is accurate at the time you view it. However, we cannot and have not checked the accuracy of all information provided by outside sources or by the providers of other information or of other parties linked to or from the website. We would recommend that you contact the Authority to check the status of an application and for confirmation regarding any decision made on an

application. Confirmation of a decision will be provided to the applicant or agent in writing.

NP/CEC/0323/0256

P11633

P11069

P8246

P8246

P2928

P3289

P9250

P8135

P8135

P7836

NP/DDD/0322/0455

NP/DDD/0322/0455

NP/DDD/0323/0230

NP/DDD/0423/0398

NP/DDD/0423/0451

NP/DDD/0423/0461

NP/DDD/0423/0462

NP/DDD/0423/0465

NP/DDD/0423/0468

NP/DDD/0423/0469

NP/DDD/0523/0571

NP/DDD/0523/0573

NP/DDD/0623/0731

NP/DDD/0723/0761

NP/DDD/0723/0857

NP/DDD/0723/0875

NP/DDD/0723/0876

NP/DDD/0823/0890

NP/DDD/0823/0896

NP/DDD/0823/0900

NP/DDD/0823/0902

NP/DDD/0823/0920

NP/DDD/0823/0924

NP/DDD/0823/0926

NP/DDD/0823/0948

NP/DDD/0823/0949

NP/DDD/0823/0968

NP/DDD/0823/0989

NP/DDD/0823/0999

NP/DDD/0923/1080

NP/DIS/0123/0087

NP/DIS/0623/0636

NP/DIS/0623/0637

NP/DIS/0723/0797

P11037 + 11040

NP/DIS/0723/0798

P11037 + 11040

NP/DIS/0723/0835

NP/DIS/0723/0871

NP/DIS/0723/0872

NP/DIS/0823/0939

NP/DIS/0823/0952

NP/DIS/0823/0970

NP/DIS/0923/1027

P7510 + 2372 +

P3250

P9579

P9579

P4822

1225

P957

P8744

P6040+7264

P6040+7264

P2186

P5988

P2562

P4201

P6627

P11901

P1400

P6171

P4629

P10051

P5987

P4372

P2280 + 6191

P2280 + 6191

P8565 + 5773

P2562

P5437 + 916

P5437 + 916

P5328

P874

P8233

**Hurdlow Hall** 

Hartington Middle Quarter

the Manor House, Froggatt.

the Manor House, Froggatt.

Rock Mill Business Park Stoney Middleton

Hollington End Farm

The Ashford Arms

existing premises

The Ashford Arms

Extensions and alterations

Conversion to two residential houses

Erection of single-storey rear extension.

associated internal and external works.

Thorpe

Ashford

**Ashford** 

Silver Trees Hathersage

Haig House Bakewell

Haig House Bakewell

The Old Toll Bar

Foolow

agricultural.

Wheston

Ashford

The Cottage Winster

School House Edensor

**Shakerley House Great Longstone** 

existing conservatory.

Shakerley House **Great Longstone** 

(Lumford Bridge). **Lumford Bridge** Bakewell

East Leigh Winster

Winster

School House Edensor

7 Mayfield Terrace Hathersage

Wheatlands

Baslow & Bubnell

Imsworth Cottage

covered slurry tank

Hartington Middle Quarter

space for new bedroom.

Quiet Woman Inn Hartington Middle Quarter

Hall Bungalow

South Darley

Thorpe House Thorpe

Woodbine Cottage

Cow Close Cottage Hathersage

Stanage House Farm

**Rutland Chambers** 

**Rutland Chambers** 

Calver

Eyam

Bakewell

Bakewell

Old Vicarage

Old Vicarage Edensor

Moor Top Farm Hollinsclough

Calver

Calver

Bakewell

The Meads

Fawfieldhead

Castern Hall llam

Edale

Knouchley Farm Cottage

**Knouchley Farm Cottage** 

Riverside Business Park

Barn to the east of the B5053

Edensor

Proposed alterations and extension.

Moscar Farm

Bakewell

Carpenters Cottage

natural stone wall and timber window.

Demolition of existing conservatory to rear of property.

Erection of single storey summerhouse in garden.

modified rear entrance door and new fire surrounds.

Oil tank with 100mm concrete base and supply pipework

Listed Building Consent - Proposed solar panel installation

Discharge of Condition 12 on NP/DDD/0620/0475.

Discharge of conditions 3 and 4 on NP/DDD/0621/0598.

Discharge of conditions 3 and 4 on NP/DDD/0621/0599.

Discharge of conditions 5,6 and 10 on NP/DDD/0622/0817

Discharge of conditions 8 and 13 on NP/SM/0522/0682.

Discharge of Conditions 12, 13 & 15 to NP/DDD/1019/1103

Discharge of conditions 3, 4 and 9 on NP/HPK/1121/1225.

Discharge of conditions 3a, 7, 10 and 15 on NP/SM/0123/0072.

Discharge of Condition 9 to NP/DDD/1019/1101.

Discharge of condition 27 on NP/DDD/1122/1399.

Discharge of condition 3a on NP/SM/0423/0447.

Discharge of conditions on 3, 4, 7, 8 and 12 on NP/DDD/0622/0818.

Erection of single storey, flat roofed brick and stone infill extension.

Listed Building consent - General refurbishment to property including

replacement/alteration of windows, including new conservation skylight,

Resubmission of application ref: NP/DDD/0622/0844 to increase the size of the

Demolition of toilet block. new pitched roof building to replace toilet block to

Demolition of existing stables and erection of a new building with associated

works to provide ancillary accommodation, works of hard and soft landscaping.

house new toilets including disabled and baby change facility along with amenity

Land To The East Of

**Brookfield Grove** 

Proposed single storey rear extension

Conversion of garage to living accommodation

New terrace and landscaping around the house

'Agricultural building to house fodder and machinery'

Demolition of lean to porch and replacement with new porch

The Manor House

The Manor House

Curbar

Froggatt

Newlands Hathersage

	Waddesheld Forest	
NP/CEC/0323/0256	Proposed change in design to extant garden room addition and additional linking single storey extension between garden room and existing kitchen outrigger and associated alterations	Granted Conditionally
P11633	Cut Thorn Farm Wildboarclough	
NP/CEC/0523/0567	Proposed conversion and alteration of barn to form one dwelling with access, parking and external works.	Granted Conditionally
P3568 + 9164	Lamaload Forest Barn Macclesfield Forest	
NP/DDD/0123/0079	Proposed agricultural livestock building with underfloor slurry store extension and new access track	Granted Conditionally
P11084	The National Trust Monyash House Farm Monyash	

	Macclesfield Forest	
NP/DDD/0123/0079	Proposed agricultural livestock building with underfloor slurry store extension and new access track	Granted Conditionally
P11084	The National Trust Monyash House Farm Monyash	
NP/DDD/0223/0204	Window repair and replacement, reconfiguration of interior layout, new doors, new limecrete floor, glazed link and conversion of former agricultural building to farm office and additional bedroom above.	Granted Conditionally
P11069	Hurdlow Hall Hartington Middle Quarter	
NP/DDD/0223/0206	Listed Building consent -Window repair and replacement, reconfiguration of interior layout, new doors, new limecrete floor, glazed link and conversion of former agricultural building to farm office and additional bedroom above.	Granted Conditionally
	ionio agriculta sallang to laim onios and daditional bodioon abovo.	

Retrospective planning application for new wildlife pond within the grounds of

Retrospective planning application for new wildlife pond within the grounds of

S.73 application for the variation of condition 1 and 54 on NP/DDD/1021/1162

New internal and external refurbishment scheme to existing premises

Listed Building consent - Conversion to two residential houses

Creation of new access and change of use of land to mixed-use equestrian and

Erection of rear extension and alterations to existing dormer roof/window with

Listed Building consent - rear/north gable - rebuild chimney stack and reline.

Repair eroded stone work. Front elevation window - to replace with windows like for like as per all the windows on that gable and repair lintel, sills and jamb.

Listed Building consent - Removal of modern infill of rear wall and aluminium

Erection of a timber framed conservatory replacing existing conservatory.

Listed Building consent - Erection of a timber framed conservatory replacing

Listed Building consent - Erection of two bollards on the Bridge Over River Wye

Listed Building consent - New front door as suggested by conservation officer.

Listed Building Consent - Paint external surfaces of both front doors and both

Removal of tile cladding, aluminium windows and render and replace with

back doors green (specifically Little Greene Paints 'Jewel Beetle').

windows and replace with stone to match original and window to match existing

Listed Building Consent - New internal and external refurbishment scheme to

P2007       As         NP/DIS/0923/1048       Di         P8744       Ci         NP/DIS/0923/1056       Di         P4401       His         NP/DIS/0923/1118       Di         P8744       Ci         NP/DIS/0923/1120       Di         P8744       Ci         NP/DIS/0923/1153       Di         P4239       W         O       Ci         NP/DIS/1023/1208       Di         P3450       Ci         NP/GDO/0523/0550       Gara         P4358       Ec         NP/GDO/0823/0934       Ai         P1640 + 818       Fi         NP/HPK/0323/0325       Li         NP/HPK/0323/0325       Li         P3311       Si         NP/HPK/0623/0617       Pi         P3386 + 8757       Re         P3386 + 8757       Ci	ischarge of condition 8 and 11 on NP/SM/0423/0447.  astern Hall  ischarge of conditions 8 and 11 on NP/SM/0423/0447.  astern Hall  ischarge of condition 6 on NP/DDD/0820/0805  oby Trinity Church  fanton-In-Peak  ischarge of Condition 4a on NP/SM/0423/0446  astern Hall  am  ischarge of Condition 15 on NP/SM/0423/0446  astern Hall  am  ischarge of Condition 3 and 5 on NP/DDD0323/0329.  findyridge  reat Longstone  ischarge of Condition 8 on NP/DDD0/0223/0149  otesfield Farm  artington Middle Quarter  ischarge of Condition 6, 11 and 12 on NP/DDD0/0623/0718  hee Tor  akewell  PDO Notification - The installation of a 17.5m tower supporting 3 no. antennas  nd 2 no. 0.6m dishes; 1 no. equipment cabinet, 1 no. meter cabinet and  cultury development thereto including a generator and a 1.1m dyshone wall  impound for the Shared Rural Network project on behalf of Cornerstone.  and at Lane Head Green  date  pplication for prior approval of a proposed temporary recreational campsite in  ood zone 2 or 3.  and to the East of Bamford Tennis Club  hornhill  sted Building consent - Internal alterations to annexe to remove the existing  wimming pool and replace it with ancillary accommodation incidental to the  ain dwelling.  Park Crescent  ayfield  eplacement of existing conservatory with a single storey structure within the  disting conservatory footprint.  tuterfield House  amond At Furlongs Farm	Condition/s Partly Discharged  Condition/s Partly Discharged
P8744       Callate         NP/DIS/0923/1056       Diamond         P4401       History         NP/DIS/0923/1118       Diamond         P8744       Callate         NP/DIS/0923/1120       Diamond         P8744       Callate         NP/DIS/0923/1153       Diamond         P4239       W         NP/DIS/1023/1208       Diamond         P3450       Callate         NP/GDO/0523/1220       Diamond         P1354C       Callate         NP/GDO/0523/0550       Garan         NP/GDO/0823/0934       Allate         P1640 + 818       Fine         NP/HPK/0323/0325       Listery         P3311       Bistery         NP/HPK/0523/05555       Reserved         P3137       Bistery         NP/HPK/0623/0617       Printery         P3386 + 8757       Callate         NP/HPK/0623/0617       Printery         P3386 + 8757       Callate	astern Hall am  ischarge of condition 6 on NP/DDD/0820/0805  oly Trinity Church tanton-in-Peak  ischarge of Condition 4a on NP/SM/0423/0446  astern Hall am  ischarge of Condition 15 on NP/SM/0423/0446  astern Hall am  ischarge of Conditions 3 and 5 on NP/DDD0323/0329.  //indyridge reat Longstone  ischarge of Condition 8 on NP/DDD0/0223/0149  otesfield Farm artington Middle Quarter  ischarge of Condition 6, 11 and 12 on NP/DDD/0623/0718  hee Tor askewell  PDO Notification - The installation of a 17.5m tower supporting 3 no. antennas and 2 no. 0.6m dishes; 1 no. equipment cabinet, 1 no. meter cabinet and ncillary development thereto including a generator and a 1.1m drystone wall smpound for the Shared Rural Network project on behalf of Cornerstone.  and at Lane Head Green dale  pplication for prior approval of a proposed temporary recreational campsite in cod zone 2 or 3. leids Farm eak Forest  pplication for prior approval of a proposed temporary recreational campsite in cod zone 2 or 3. leids Farm eak Forest  pplication for prior approval of a proposed temporary recreational campsite in cod zone 2 or 3. leids Farm eak Forest  pplication for prior approval of a proposed temporary recreational campsite in cod zone 2 or 3. leids Farm eak Forest  pplication for prior approval of a proposed temporary recreational campsite in cod zone 2 or 3. leids Farm eak Forest  pplication for prior approval of a proposed temporary recreational campsite in cod zone 2 or 3. leids Farm eak Forest  pplication for prior approval of a proposed temporary recreational campsite in cod zone 2 or 3. leids Farm eak Forest  pplication for prior approval of a proposed temporary recreational campsite in cod zone 2 or 3. leids Farm eak Forest  pplication for prior approval of a proposed temporary recreational campsite in cod zone 2 or 3. leids Farm eak Forest	Condition/s Partly Discharged  Candition/s Partly Discharged  Condition/s Partly Discharged  Condition/s Partly Discharged  Condition/s Partly Discharged  Refused  Refused  Granted Conditionally
P4401       Head of the standard of th	observed of Condition 4a on NP/SM/0423/0446 astern Hall am ischarge of Condition 15 on NP/SM/0423/0446 astern Hall am ischarge of Conditions 3 and 5 on NP/DDD0323/0329. //indyridge reat Longstone ischarge of Conditions 8 on NP/DDD0323/0329. //indyridge reat Longstone ischarge of Condition 8 on NP/DDD/0223/0149 obesfield Farm artington Middle Quarter ischarge of Condition 6, 11 and 12 on NP/DDD/0623/0718 hee Tor akewell  PDO Notification - The installation of a 17.5m tower supporting 3 no. antennas nd 2 no. 0.6m dishes; 1 no. equipment cabinet, 1 no. meter cabinet and notillary development thereto including a generator and a 1.1m drystone wall smpound for the Shared Rural Network project on behalf of Cornerstone. and at Lane Head Green date  pplication for prior approval of a proposed temporary recreational campsite in load zone 2 or 3. elds Farm eak Forest  pplication for prior approval of a proposed temporary recreational campsite in load zone 2 or 3. and to the East of Bamford Tennis Club hornhill  sted Building consent - Internal alterations to annexe to remove the existing wimming pool and replace it with ancillary accommodation incidental to the lain dwelling. Park Crescent ayfield  eplacement of existing conservatory with a single storey structure within the disting conservatory footprint. utterfield House amford	Condition/s Partly Discharged  Refused  Refused  Granted Conditionally  Granted Conditionally
P8744       Callate         NP/DIS/0923/1120       Diameter         P8744       Callate         NP/DIS/0923/1153       Diameter         P4239       W         NP/DIS/1023/1208       Diameter         P3450       Callate         NP/DIS/1023/1220       Diameter         P1354C       Callate         NP/GDO/0523/0550       Garate         NP/GDO/0823/0934       Allate         P1640 + 818       Fine         NP/HPK/0323/0325       Liang         NP/HPK/0323/0325       Liang         NP/HPK/0523/0555       Resemble         P3137       Biameter         NP/HPK/0623/0617       Print Lang         P3386 + 8757       Callate	ischarge of Condition 15 on NP/SM/0423/0446 astern Hall am ischarge of Conditions 3 and 5 on NP/DDD0323/0329.  I/indyridge reat Longstone ischarge of Condition 8 on NP/DDD/0223/0149 otesfield Farm artington Middle Quarter ischarge of Condition 6, 11 and 12 on NP/DDD/0623/0718 hee Tor akewell  PDO Notification - The installation of a 17.5m tower supporting 3 no. antennas nd 2 no. 0.6m dishes; 1 no. equipment cabinet, 1 no. meter cabinet and ncillary development thereto including a generator and a 1.1m drystone wall be be and at Lane Head Green date pplication for prior approval of a proposed temporary recreational campsite in bod zone 2 or 3. and to the East of Bamford Tennis Club hornhill sted Building consent - Internal alterations to annexe to remove the existing wimming pool and replace it with ancillary accommodation incidental to the ain dwelling. Park Crescent ayfield eplacement of existing conservatory with a single storey structure within the disting conservatory footprint. utterfield House amford	Condition/s Partly Discharged  Condition/s Partly Discharged  Condition/s Partly Discharged  Condition/s Partly Discharged  Refused  Refused  Granted Conditionally
P8744       Callate         NP/DIS/0923/1153       Die         P4239       W         NP/DIS/1023/1208       Die         P3450       Callate         NP/DIS/1023/1220       Die         P1354C       Callate         NP/GDO/0523/0550       Garate         P4358       Ed         NP/GDO/0823/0934       Ale         P1640 + 818       File         P6826       Tr        NP/HPK/0323/0325       Lie         P3311       See         NP/HPK/0523/0555       Ree         P3137       Bie         NP/HPK/0623/0617       Print         P3386 + 8757       Callate	ischarge of Conditions 3 and 5 on NP/DDD0323/0329.  //indyridge reat Longstone  ischarge of Condition 8 on NP/DDD0223/0149  otesfield Farm artington Middle Quarter  ischarge of Condition 6, 11 and 12 on NP/DDD/0623/0718  hee Tor akewell  PDO Notification - The installation of a 17.5m tower supporting 3 no. antennas nd 2 no. 0.6m dishes; 1 no. equipment cabinet, 1 no. meter cabinet and ncillary development thereto including a generator and a 1.1m drystone wall ompound for the Shared Rural Network project on behalf of Cornerstone.  and at Lane Head Green dale  pplication for prior approval of a proposed temporary recreational campsite in load zone 2 or 3.  leids Farm eak Forest  pplication for prior approval of a proposed temporary recreational campsite in load zone 2 or 3.  and to the East of Bamford Tennis Club hornhill  sted Building consent - Internal alterations to annexe to remove the existing wimming pool and replace it with ancillary accommodation incidental to the ain dwelling.  Park Crescent ayfield  eplacement of existing conservatory with a single storey structure within the sisting conservatory footprint.  utterfield House amnford	Condition/s Partly Discharged  Condition/s Partly Discharged  Condition/s Partly Discharged  Refused  Refused  Granted Conditionally  Granted Conditionally
P4239 W G G S S S S S S S S S S S S S S S S S	individige reat Longstone read Longs	Condition/s Partly Discharged  Condition/s Partly Discharged  Refused  Refused  Granted Conditionally  Granted Conditionally
P3450 C. Hailand P. Ha	obesfield Farm artington Middle Quarter  ischarge of Condition 6, 11 and 12 on NP/DDD/0623/0718  hee Tor akewell  PDO Notification - The installation of a 17.5m tower supporting 3 no. antennas and 2 no. 0.6m dishes; 1 no. equipment cabinet, 1 no. meter cabinet and nocillary development thereto including a generator and a 1.1m drystone wall ompound for the Shared Rural Network project on behalf of Cornerstone. and at Lane Head Green dale  pplication for prior approval of a proposed temporary recreational campsite in ood zone 2 or 3. leids Farm eak Forest  pplication for prior approval of a proposed temporary recreational campsite in lood zone 2 or 3. and to the East of Bamford Tennis Club hornhill  sted Building consent - Internal alterations to annexe to remove the existing wimming pool and replace it with ancillary accommodation incidental to the ain dwelling. Park Crescent ayfield  eplacement of existing conservatory with a single storey structure within the kisting conservatory footprint. utterfield House amford  roposed agricultural building to house and lamb sheep and to store fodder and applements and At Furlongs Farm	Condition/s Partly Discharged  Refused  Refused  Granted Conditionally  Granted Conditionally
NP/DIS/1023/1220 Display	ischarge of Condition 6, 11 and 12 on NP/DDD/0623/0718  hee Tor akewell  PDO Notification - The installation of a 17.5m tower supporting 3 no. antennas and 2 no. 0.6m dishes; 1 no. equipment cabinet, 1 no. meter cabinet and notillary development thereto including a generator and a 1.1m drystone wall ompound for the Shared Rural Network project on behalf of Cornerstone. and at Lane Head Green dale  pplication for prior approval of a proposed temporary recreational campsite in load zone 2 or 3. ields Farm leak Forest  pplication for prior approval of a proposed temporary recreational campsite in load zone 2 or 3. and to the East of Bamford Tennis Club hornhill  sted Building consent - Internal alterations to annexe to remove the existing wimming pool and replace it with ancillary accommodation incidental to the lain dwelling.  Park Crescent ayfield  eplacement of existing conservatory with a single storey structure within the kisting conservatory footprint. utterfield House amford  roposed agricultural building to house and lamb sheep and to store fodder and aplements and At Furlongs Farm	Refused  Refused  Granted Conditionally  Granted Conditionally
P4358	and 2 no. 0.6m dishes; 1 no. equipment cabinet, 1 no. meter cabinet and incillarly development thereto including a generator and a 1.1m drystone wall compound for the Shared Rural Network project on behalf of Cornerstone. and at Lane Head Green dale  pplication for prior approval of a proposed temporary recreational campsite in cood zone 2 or 3. selds Forest  pplication for prior approval of a proposed temporary recreational campsite in cood zone 2 or 3. and to the East of Bamford Tennis Club hornhill  sted Building consent - Internal alterations to annexe to remove the existing wimming pool and replace it with ancillary accommodation incidental to the ain dwelling.  Park Crescent ayfield  eplacement of existing conservatory with a single storey structure within the kisting conservatory footprint. utterfield House amford  roposed agricultural building to house and lamb sheep and to store fodder and applements and At Furlongs Farm	Refused  Granted Conditionally  Granted Conditionally
P1640 + 818 Fi P6  NP/GDO/0923/1025 Ap P6826 La Th  NP/HPK/0323/0325 Li sv m  P3311 3 Hi  NP/HPK/0523/0555 Re P3137 Bi Bi  NP/HPK/0623/0617 Pi P3386 + 8757 La Ci	and to the East of Bamford Tennis Club hornhill  sted Building consent - Internal alterations to annexe to remove the existing wimming pool and replace it with ancillary accommodation incidental to the lain dwelling.  Park Crescent ayfield  eplacement of existing conservatory with a single storey structure within the kisting conservatory footprint.  utterfield House amford  roposed agricultural building to house and lamb sheep and to store fodder and inplements and At Furlongs Farm	Granted Conditionally  Granted Conditionally
NP/GDO/0923/1025 Apple File File File File File File File Fi	pplication for prior approval of a proposed temporary recreational campsite in lood zone 2 or 3. and to the East of Bamford Tennis Club hornhill  sted Building consent - Internal alterations to annexe to remove the existing wimming pool and replace it with ancillary accommodation incidental to the sain dwelling. Park Crescent ayfield  eplacement of existing conservatory with a single storey structure within the kisting conservatory footprint. utterfield House amford  roposed agricultural building to house and lamb sheep and to store fodder and explements and At Furlongs Farm	Granted Conditionally
NP/HPK/0323/0325 Li sv m m P3311 3 H: NP/HPK/0523/0555 Rep P3137 Bi B: NP/HPK/0623/0617 P1 im P3386 + 8757 Li Ci Ci sv m m m m m m m m m m m m m m m m m m	sted Building consent - Internal alterations to annexe to remove the existing wimming pool and replace it with ancillary accommodation incidental to the pain dwelling.  Park Crescent ayfield  eplacement of existing conservatory with a single storey structure within the existing conservatory footprint.  utterfield House amford  roposed agricultural building to house and lamb sheep and to store fodder and explements and At Furlongs Farm	
NP/HPK/0523/0555 Re ex P3137 Bit	eplacement of existing conservatory with a single storey structure within the xisting conservatory footprint. utterfield House amford roposed agricultural building to house and lamb sheep and to store fodder and applements and At Furlongs Farm	Granted Conditionally
NP/HPK/0623/0617 Prim P3386 + 8757 La	roposed agricultural building to house and lamb sheep and to store fodder and nplements and At Furlongs Farm	
C	· ·	Granted Conditionally
	astleton  stallation of a solar photovoltaic electricity generation system with battery corage. To be installed on the South West facing part of the roof.	Granted Conditionally
P6706 25 H3 NP/HPK/0723/0851 Pr ac P6224 C	5 Pike Close ayfield roposed change of use of former photographic studio to residential ccommodation (change of use from commercial (B1/E(g)) to residential(C3)) hapelsteads Barn	Granted Conditionally
NP/HPK/0723/0869 Read	ormhill efurbishment of the disused stable block to form self-contained holiday	Refused
P2222 Ro As NP/HPK/0823/0925 Ex	ound Meadow Barn ston xtension to existing agricultural building.	Granted Conditionally
P3046 Ro Cl	edgate End Farm Cottage hinley, Buxworth & Brownside roposed extension to existing automotive garage to create additional storage	Granted Conditionally
P4377 Ri Ba	nd workshop space. iverside Garage amford roposed change of use of land to allow stationing of shepherd's hut	Granted Conditionally
P9784 St H:	etrospective). toop Farm artington Upper Quarter	·
P6730 Ba	astallation of 9 kiosks and 3 buildings amford Water Treatment Works amford	Granted Conditionally
Ni cc ac ex as ar	.19 application for the removal or variation of conditions 2, 3, 4 and 5 on P/HPK/0420/0302 - Conversion of the large barn to one residential dwelling, conversion of the small barn to ancillary commodation/holiday accommodation to Chestnut Farmhouse, internal and atternal works to the barns and house, change of use of the associated land to residential, works of hard and soft landscaping, car parking, and other works incidental to the application proposals.	Granted Conditionally
NP/HPK/1222/1522 S. 10 re ac Ci ch ar pr	hapel-en-le-Frith  7.73 application for the removal or variation of conditions 2, 3, 4, 5, 6, 7, 8, 9, 0, 11 and 24 on NP/HPK/0420/0301 - Conversion of the large barn to one esidential dwelling, conversion of the small barn to ancillary commodation/holiday accommodation to hestnut Farmhouse, internal and external works to the barns and house, mange of use of the associated land to residential, works of hard and soft landscaping, car parking, and other works incidental to the application roposals.	Granted Conditionally
NP/K/0421/0383 Cr www.ar	hestnut Centre hapel-en-le-Frith  reation of vehicular access from Woodhead Road. Parking for one vehicle hen required and new dry stone boundary wall. Removal of barb wire fencing and levelling of ground. he Mistal Barn	Granted Conditionally
NP/NMA/0923/1043 No de st	olme Valley  on-material amendment to NP/HPK/1013/0898: Modification of Stage 2 quarry evelopment commencement date to bring forward the operation of soil ripping to facilitate quarrying and variation of soil placement process ld Moor Quarry (Tunstead)	Amendments Accepted
NP/NMA/0923/1105 Ne go cl:	on-Material Amendment to NP/HPK/0919/1018 - Install cast iron rainwater cods in lieu of uPVC rainwater goods. Reinstate the existing Staffordshire Blue ay roof ridge tiles in lieu of concrete ridge tiles.	Amendments Accepted
NP/NMA/0923/1138 No ou re	on-material amendment on NP/HPK/0721/0728 - Amendment to elevations of utbuilding to show the removal of the timber fascia boards and to accurately effect the ground level to the rear (outside the red edge) unters Barn	Amendments Accepted
NP/NMA/0923/1162 No wi lig P9807 Hi	on Material Amendments to NP/DDD/1022/1263: Introduction of 1No. slot indow to side elevation within entrance recess and amendment of 1No. roof ght RL03 - size altered to suit room internally. illcroft ideswell	Amendments Accepted
NP/NMA/1023/1219 No or su	on-material amendment to NP/DDD/0623/0597 - In relation to part 2 of the riginal consent (to erect a greenhouse) to replace the proposed greenhouse as ubmitted with a smaller structure on the same site and to be used for the same urposes.  the Old House	Amendments Accepted
NP/S/0123/0090 O w P10993 W	vinster  utline application with all matters except access reserved for 1 no. dwelling on ooded site.  /ooded area to the north of Kirk Edge Road radfield	Refused
NP/S/0723/0873 S. 12 P1076 Si	.73 application for the removal or variation of conditions 2, 3, 7, 9, 10, 12, 13, 4, 15, 17 and 17A on NP/S/0818/0705 ite of Far Nova	Granted Conditionally
NP/SM/0423/0393 Cl bu dr al	heffield  hange of use from recreation barn to holiday let requiring no exterior work to uilding. Underfloor heating, plumbing, electrical services and rainage all in place as well as shower room and toilet. Some minor interior terations, such as replacing paddle stairs with a conventional flight and stallation of electric cooker.	Refused
P6201 Ki SI NP/SM/0523/0485 La	nowsley Cross Farm heen awful development certificate for proposed non material change of use from	LDC Granted
us pe ho Th of gu	se as a single dwellinghouse to use as a holiday let for not more than 9 ersons and 5 cars (within use class C3). Such persons forming a single busehold for not more than 28 days in any calendar year.  The proposed non material change of use does not include use as a gathering for people for social, pleasure, amusement or entertainment; or for invited usets.	
P5051 U <sub>I</sub> Al  NP/SM/0723/0825 CI	pper Hurst Istonefield hange of use from a public house and residential to one residential dwelling.	Refused
P2784 TH Q	o internal or external changes to be made. he Knights Table uarnford rection of agricultural building to house livestock, store feed, fodder and	Refused
P10574 Fr	emoval of field shelters and storage container. rith Cottage eekfrith	
P10128 Bi	Replacement window to front elevation of dwelling' rown End Farm /aterhouses roposed change of use of land to allow mix of agriculture, keeping and grazing	Granted Conditionally  Granted Conditionally
of ar P3873 Th	roposed change of use of land to allow mix of agriculture, keeping and grazing for horses, keeping of homing pigeons, and the erection of two timber buildings incillary to this use.  The Barn  The Barn Arslow & Elkstone	Granted Conditionally
P11386 Ni	roposed garage (detached) - resubmission of previously approved application P/SM/0722/0991 with amended position of garage. he Old Rectory rindon	Granted Conditionally
NP/SM/0923/1020 AI P7279 W	Iterations and a two storey side extension with associated development. /est Lodge eaton	Granted Conditionally
P779 Bi	stallation of external flue irchcroft /arslow & Elkstone	Granted Conditionally
C <sub>i</sub> b. Lt	Complete removal of sycamore tree (numbered T4 in ProHort Ltd's report) at oronation Gardens, Bamford Removal of some dead wood from lime trees (numbered T1 & T2 in ProHort td's report) at the Green, Bamford oronation Gardens	Accept
NP/TCA/0823/0903 To in	amford o complete trimming of 3 trees at the front of the Rambler Inn. 2 trees together a garden area to have work done to the lower branches over the pavement	Accept
ar re P3514 Ra	and seating area. Tree to the right hand side of entrance to have a heavy eduction done to get branches away from cables etc ambler Inn dale	
ar As ar El ar P11274 Ba	sh (T1) - Fell. This tree is less than 1m from a listed barn, and the branches re overhanging the roof. sh (T2) - Fell. This tree is less than 1m from a listed barn, and the branches re overhanging the roof. Ider (T3) - Fell. This tree is less than 1m from a listed barn, and the branches re overhanging the roof. arns to the South of Green Farm	Accept

	Applications determined by the Head of Development Control between	
NP/TCA/0923/1070	01/10/2023 and 31/10/2023  G1 - Group of Thuja & Leylandii - Felling due to spread of root system begging to cause damage to retaining wall which upholds bank above house. Damage	Accept
	so far has resulted in water movement into property.  T1 - Beech - Dismantle & removal to ground level due to structural cracking in stone building (garage/outhouse) at base of tree, sever lean over roof.	
	T2 - Sycamore - Dismantle & removal to ground level due to structural cracking in stone building (garage/outhouse) at base of tree.  T3 - Beech - Dismantle & removal to ground level due to structural cracking in	
D.4000	stone building (garage/outhouse) at base of tree.  T4 - Beech. Fairly small tree of which half of tree is dead due to fire damage caused by previous owners. Dismantle & removal to ground level.	
P1682 NP/TCA/0923/1079	The Pastures Hope  (T1) Dismantle Russian vine clad spruce.	Accept
	<ul> <li>(T2) Cut the vine growing across the barn off at head height and floor. Vine growing up the house to cut a couple of feet at the bottom and let die off.</li> <li>(T3) Dismantle Ash and willow in between barns. (Customer has already applied for planning on this tree we believe)</li> </ul>	
P11274	(T4) Fell small elder. (Customer has already applied for planning on this tree we believe) Green Farm Middleton & Smerrill	
NP/TCA/0923/1088	Reduction of Conifers around property Reduce Maple tree by 2/3 metres to old pruning points Reduce Sycamore tree by 2/3 metres	Accept
P10436 NP/TCA/0923/1099	The Shires Alstonefield Silver Birch Tree overhanging the property at 33 The Crofts and over the public	Accept
P2742	footpath. The tree stands at approximately 14m. Proposed works of section felling. At the rear of 33 The Crofts Hathersage	, toogp.
NP/TCA/0923/1109	To fell 5 no Cypress trees in rear garden of Westfield Cottage. The trees are causing serious shading issues to Westfield Cottage & other neighbouring properties. Also, causing serious issues with blocked gutters & drainpipes in the	Accept
	immediate adjacent properties, namely: The Smithy, The Workshops & The Blacksmiths. All owners have requested trees to be felled.  The 5 no Cypress trees will be felled by a qualified arborist - Ecotrees of Sheffield. The Cypress trees are of low amenity value, are non-native and wholly	
P908	inappropriate in a conservation area in the town of Bakewell, in the heart of the Peak District National Park. Once felled, the trees will be replaced with a native species hedgerow which will be maintained to a heigh of circa 2 metres once established. This will be of greater ecological benefit.  Westfield Cottage	
NP/TCA/0923/1114	Bakewell  Fell or leave sycamore as a monolith pole of <4m height.	Accept
P6041 NP/TCA/0923/1126	The Hayes Telecommunications Mast Bakewell  T1, T2 Cypress - Fell, dying. Replant in autumn, species not yet decided.	Accept
P6032	T3 Blue Cedar - Carry out a crown thin removing weight from branches due to large branches failing, remove deadwood Burre House Bakewell	
NP/TCA/0923/1134	The client has requested for me to remove an Ash tree in the front yard that has obvious evidence that is is suffering from Ash dieback (Hymenoscyphus fraxineus) due to the amount of dead foliage/branches in the canopy.	Accept
P11061 NP/TCA/0923/1135	Old Hall Farm Foolow  T1 Yew - Reduce crown by approx 1-2m to suitable growing points	Accept
	T2 Elm - Reduce by approx 0.5m Raise crown over hedge and driveway to balance T3 Yew - Reduce crown by approximately 1m T4 Lime - Remove epicormics and clear stem up to crown break. T6 Lime - Clear stem up to crown break and raise crown to 6m	
P474	G7 2x sycamores - Raise crowns to 6m G8 Hawthorns - Approx 6 trees fell and grind out stumps where possible G9 Mixed species - Approx 6 trees. Remove and grind stumps where possible 5 Castle Hill	
NP/TCA/0923/1140 P4228	Bakewell  Tree Survey and plan The Vicarage	Accept
NP/TCA/0923/1141	Hathersage T1- Thuja - crown lift to height of 7 metres	Accept
P7435	T2 to T5 - Ash, Alder, Willow on stream bank - fell T6 - Ash - on roadside - fell Victoria Mill Bakewell	
NP/TCA/0923/1150	T1- Cypress - To hedge cut new growth top and sides. T2- Ash -To reduce crown by approx. 3m. G3 - Sycamore group - To re-pollard x2 Sycamore and reduce height of x1	Accept
P3687	Sycamore by approx. 3m. Hawthorne Cottage Hartington Town Quarter	
NP/TCA/0923/1151 P7919	Horse Chestnut Tree - Fell because Horse Chestnut 'blight' in this tree. Replace with a Cobnut tree. Peter Leigh & Sons Rainow	Accept
NP/TCA/1023/1172 P1859	T1 - Laburnum - Reduce by 25% due to the poor unions. Church Lea Stanton-In-Peak	Accept
NP/TCA/1023/1173	Dismantle the 3 Holly Trees due to them being poor specimens Dismantle the 1 Damson due to safety concerns Seven Oaks	Accept
NP/TCA/1023/1174	Eyam  T1 - Cherry - Dismantle due to the decay at the base and proximity to the road  T2 - Copper Beech - Dismantle as it has outgrown its location and close	Accept
	proximity to the road T3 - Rowan - Dismantle due its close proximity to the neighboring property, shading of the garden and obstructing views T4 - Malus - Dismantle to ground level as is a poor specimen	
P10325	REPLANTING - 6 various trees already purchased to be planted during the dormant season Fern Hollow House Eyam	
NP/TCA/1023/1177 P9994	G1 - Row of Beech and Ash - Prune back the overextending branches to suitable replacement growth points to reduce the overhang into the garden.  The Gables	Accept
ND (TO ) (1000 (1100	Baslow & Bubnell  T1 & T2 - Himalayan Birch - Crown lift.	Accept
NP/TCA/1023/1180	T3 - Elm - Crown lift to the line.	
NP/TCA/1023/1180 P5419 NP/TCA/1023/1186	T3 - Elm - Crown lift to the line. Cherry Tree Farm Baslow & Bubnell  Photographs of Group 9 (screen grabs from surveyor video), Group 8 (screen	Accept
P5419	T3 - Elm - Crown lift to the line. Cherry Tree Farm Baslow & Bubnell	Accept
P5419 NP/TCA/1023/1186	T3 - Elm - Crown lift to the line. Cherry Tree Farm Baslow & Bubnell  Photographs of Group 9 (screen grabs from surveyor video), Group 8 (screen grabs from surveyor video) and Tree 865. Location map.Castleton Tree Safety Survey Tables. non provided Castleton  Shown in the photographs are two sycamores I am requesting to remove one is a smaller damaged one on the boundary. The larger one is completely taking over the garden and is now too big for its location and proximity to the house.	Accept
P5419  NP/TCA/1023/1186  P	T3 - Elm - Crown lift to the line. Cherry Tree Farm Baslow & Bubnell  Photographs of Group 9 (screen grabs from surveyor video), Group 8 (screen grabs from surveyor video) and Tree 865. Location map.Castleton Tree Safety Survey Tables. non provided Castleton  Shown in the photographs are two sycamores I am requesting to remove one is a smaller damaged one on the boundary. The larger one is completely taking	·
P5419  NP/TCA/1023/1186  P  NP/TCA/1023/1189	T3 - Elm - Crown lift to the line. Cherry Tree Farm Baslow & Bubnell  Photographs of Group 9 (screen grabs from surveyor video), Group 8 (screen grabs from surveyor video) and Tree 865. Location map.Castleton Tree Safety Survey Tables. non provided Castleton  Shown in the photographs are two sycamores I am requesting to remove one is a smaller damaged one on the boundary. The larger one is completely taking over the garden and is now too big for its location and proximity to the house. Shown in the photograph you can see that the trunk splits into co-dominant leaders but with a very tight union which will potentially be a weak point in the future. Due to its proximity to the property this will have terrible consequences if it were to fail. Rock House Monyash  Shown in the photographs are a number of self set sycamores that have been	
P5419  NP/TCA/1023/1186  P  NP/TCA/1023/1189  P11305	T3 - Elm - Crown lift to the line. Cherry Tree Farm Baslow & Bubnell  Photographs of Group 9 (screen grabs from surveyor video), Group 8 (screen grabs from surveyor video) and Tree 865. Location map.Castleton Tree Safety Survey Tables. non provided Castleton  Shown in the photographs are two sycamores I am requesting to remove one is a smaller damaged one on the boundary. The larger one is completely taking over the garden and is now too big for its location and proximity to the house. Shown in the photograph you can see that the trunk splits into co-dominant leaders but with a very tight union which will potentially be a weak point in the future. Due to its proximity to the property this will have terrible consequences if it were to fail. Rock House Monyash	Accept
P5419  NP/TCA/1023/1186  P  NP/TCA/1023/1189  P11305  NP/TCA/1023/1190	T3 - Elm - Crown lift to the line. Cherry Tree Farm Baslow & Bubnell  Photographs of Group 9 (screen grabs from surveyor video), Group 8 (screen grabs from surveyor video) and Tree 865. Location map.Castleton Tree Safety Survey Tables. non provided Castleton  Shown in the photographs are two sycamores I am requesting to remove one is a smaller damaged one on the boundary. The larger one is completely taking over the garden and is now too big for its location and proximity to the house. Shown in the photograph you can see that the trunk splits into co-dominant leaders but with a very tight union which will potentially be a weak point in the future. Due to its proximity to the property this will have terrible consequences if it were to fail. Rock House Monyash  Shown in the photographs are a number of self set sycamores that have been let to grow by the current tenants. As you can see they are growing directly out of the base of the wall of the shed and are in fact now starting to damage it. For this reason I request that they be removed. Grove Cottage	Accept
P5419  NP/TCA/1023/1186  P  NP/TCA/1023/1189  P11305  NP/TCA/1023/1190  P10849	T3 - Elm - Crown lift to the line. Cherry Tree Farm Baslow & Bubnell  Photographs of Group 9 (screen grabs from surveyor video), Group 8 (screen grabs from surveyor video) and Tree 865. Location map.Castleton Tree Safety Survey Tables. non provided Castleton  Shown in the photographs are two sycamores I am requesting to remove one is a smaller damaged one on the boundary. The larger one is completely taking over the garden and is now too big for its location and proximity to the house. Shown in the photograph you can see that the trunk splits into co-dominant leaders but with a very tight union which will potentially be a weak point in the future. Due to its proximity to the property this will have terrible consequences if it were to fail. Rock House Monyash  Shown in the photographs are a number of self set sycamores that have been let to grow by the current tenants. As you can see they are growing directly out of the base of the wall of the shed and are in fact now starting to damage it. For this reason I request that they be removed. Grove Cottage Wetton  T1 - Hornbeam -Reduce ( as previously done), due to obstructing the street lamp, overhanging the footpath and causing problems to the drain.	Accept
P5419  NP/TCA/1023/1186  P  NP/TCA/1023/1189  P11305  NP/TCA/1023/1190  P10849  NP/TCA/1023/1191  P1886  NP/TCA/1023/1192	T3 - Elm - Crown lift to the line. Cherry Tree Farm Baslow & Bubnell  Photographs of Group 9 (screen grabs from surveyor video), Group 8 (screen grabs from surveyor video) and Tree 865. Location map.Castleton Tree Safety Survey Tables. non provided Castleton  Shown in the photographs are two sycamores I am requesting to remove one is a smaller damaged one on the boundary. The larger one is completely taking over the garden and is now too big for its location and proximity to the house. Shown in the photograph you can see that the trunk splits into co-dominant leaders but with a very tight union which will potentially be a weak point in the future. Due to its proximity to the property this will have terrible consequences if it were to fail. Rock House Monyash  Shown in the photographs are a number of self set sycamores that have been let to grow by the current tenants. As you can see they are growing directly out of the base of the wall of the shed and are in fact now starting to damage it. For this reason I request that they be removed. Grove Cottage Wetton  T1 - Hornbeam -Reduce ( as previously done), due to obstructing the street lamp, overhanging the footpath and causing problems to the drain. T2 - Golden Conifer - Dismantle due to the close proximity to the garage' Replanting with 3 Rowans. Bridge End Close Ashford  T1 & T2 - Copper Beech & Redwood - Crown lift T3 - Cedar - Dismantle as poor condition suppressed specimen T4 - Oak - Crown lift (to the line) T5 - Ash - Dismantle as suffering from die back	Accept
P5419  NP/TCA/1023/1186  P  NP/TCA/1023/1189  P11305  NP/TCA/1023/1190  P10849  NP/TCA/1023/1191  P1886	T3 - Elm - Crown lift to the line. Cherry Tree Farm Baslow & Bubnell  Photographs of Group 9 (screen grabs from surveyor video), Group 8 (screen grabs from surveyor video) and Tree 865. Location map.Castleton Tree Safety Survey Tables. non provided Castleton  Shown in the photographs are two sycamores I am requesting to remove one is a smaller damaged one on the boundary. The larger one is completely taking over the garden and is now too big for its location and proximity to the house. Shown in the photograph you can see that the trunk splits into co-dominant leaders but with a very tight union which will potentially be a weak point in the future. Due to its proximity to the property this will have terrible consequences if it were to fail. Rock House Monyash  Shown in the photographs are a number of self set sycamores that have been let to grow by the current tenants. As you can see they are growing directly out of the base of the wall of the shed and are in fact now starting to damage it. For this reason I request that they be removed. Grove Cottage Wetton  T1 - Hornbeam -Reduce ( as previously done), due to obstructing the street lamp, overhanging the footpath and causing problems to the drain. T2 - Golden Conifer - Dismantle due to the close proximity to the garage' Replanting with 3 Rowans. Bridge End Close Ashford  T1 & T2 - Copper Beech & Redwood - Crown lift T3 - Cedar - Dismantle as poor condition suppressed specimen T4 - Oak - Crown lift (to the line)	Accept
P5419  NP/TCA/1023/1186  P  NP/TCA/1023/1189  P11305  NP/TCA/1023/1190  P10849  NP/TCA/1023/1191  P1886  NP/TCA/1023/1192  P4204C	T3 - EIm - Crown lift to the line. Cherry Tree Farm Baslow & Bubnell  Photographs of Group 9 (screen grabs from surveyor video), Group 8 (screen grabs from surveyor video) and Tree 865. Location map.Castleton Tree Safety Survey Tables. non provided Castleton  Shown in the photographs are two sycamores I am requesting to remove one is a smaller damaged one on the boundary. The larger one is completely taking over the garden and is now too big for its location and proximity to the house. Shown in the photograph you can see that the trunk splits into co-dominant leaders but with a very tight union which will potentially be a weak point in the future. Due to its proximity to the property this will have terrible consequences if it were to fail. Rock House Monyash  Shown in the photographs are a number of self set sycamores that have been let to grow by the current tenants. As you can see they are growing directly out of the base of the wall of the shed and are in fact now starting to damage it. For this reason I request that they be removed. Grove Cottage Wetton  T1 - Hornbeam -Reduce ( as previously done), due to obstructing the street lamp, overhanging the footpath and causing problems to the drain. T2 - Golden Conifer - Dismantle due to the close proximity to the garage' Replanting with 3 Rowans. Bridge End Close Ashford  T1 & T2 - Copper Beech & Redwood - Crown lift T3 - Cedar - Dismantle as poor condition suppressed specimen T4 - Oak - Crown lift (to the line) T5 - Ash - Dismantle as suffering from die back Coombs Hay Bakewell  T1 - Ash - Dismantle due to die back and close proximity to the highway. Cherry Hill Eyam	Accept Accept Accept Accept
P5419  NP/TCA/1023/1186  P  NP/TCA/1023/1189  P11305  NP/TCA/1023/1190  P10849  NP/TCA/1023/1191  P1886  NP/TCA/1023/1192  P4204C  NP/TCA/1023/1193 P7057  NP/TCA/1023/1194 P	T3 - Elm - Crown lift to the line. Cherry Tree Farm Baslow & Bubnell  Photographs of Group 9 (screen grabs from surveyor video), Group 8 (screen grabs from surveyor video) and Tree 865. Location map.Castleton Tree Safety Survey Tables. non provided Castleton  Shown in the photographs are two sycamores I am requesting to remove one is a smaller damaged one on the boundary. The larger one is completely taking over the garden and is now too big for its location and proximity to the house. Shown in the photograph you can see that the trunk splits into co-dominant leaders but with a very tight union which will potentially be a weak point in the future. Due to its proximity to the property this will have terrible consequences if it were to fail. Rock House Monyash  Shown in the photographs are a number of self set sycamores that have been let to grow by the current tenants. As you can see they are growing directly out of the base of the wall of the shed and are in fact now starting to damage it. For this reason I request that they be removed. Grove Cottage Wetton  T1 - Hornbeam -Reduce ( as previously done), due to obstructing the street lamp, overhanging the footpath and causing problems to the drain. T2 - Golden Conifer - Dismantle due to the close proximity to the garage' Replanting with 3 Rowans. Bridge End Close Ashford  T1 & T2 - Copper Beech & Redwood - Crown lift T3 - Cedar - Dismantle as poor condition suppressed specimen T4 - Oak - Crown lift (to the line) T5 - Ash - Dismantle as suffering from die back Coombs Hay Bakewell  T1 - Ash - Dismantle due to die back and close proximity to the highway. Cherry Hill Eyam  Various tree works at two location on behalf od Monyash Parish Council Fere Mere & Rake End Wood Monyash	Accept Accept Accept Accept Accept
P5419  NP/TCA/1023/1186  P  NP/TCA/1023/1189  P11305  NP/TCA/1023/1190  P10849  NP/TCA/1023/1191  P1886  NP/TCA/1023/1192  P4204C  NP/TCA/1023/1193 P7057  NP/TCA/1023/1194	T3 - EIm - Crown lift to the line. Cherry Tree Farm Baslow & Bubnell  Photographs of Group 9 (screen grabs from surveyor video), Group 8 (screen grabs from surveyor video) and Tree 865. Location map.Castleton Tree Safety Survey Tables. non provided Castleton  Shown in the photographs are two sycamores I am requesting to remove one is a smaller damaged one on the boundary. The larger one is completely taking over the garden and is now too big for its location and proximity to the house. Shown in the photograph you can see that the trunk splits into co-dominant leaders but with a very tight union which will potentially be a weak point in the future. Due to its proximity to the property this will have terrible consequences if it were to fail. Rock House Monyash  Shown in the photographs are a number of self set sycamores that have been let to grow by the current tenants. As you can see they are growing directly out of the base of the wall of the shed and are in fact now starting to damage it. For this reason I request that they be removed. Grove Cottage  Wetton  T1 - Hornbeam -Reduce ( as previously done), due to obstructing the street lamp, overhanging the footpath and causing problems to the drain. T2 - Golden Conifer - Dismantle due to the close proximity to the garage' Replanting with 3 Rowans. Bridge End Close Ashford  T1 & T2 - Copper Beech & Redwood - Crown lift T3 - Cedar - Dismantle as poor condition suppressed specimen T4 - Oak - Crown lift (to the line) T5 - Ash - Dismantle as suffering from die back Coombs Hay Bakewell  T1 - Ash - Dismantle due to die back and close proximity to the highway. Cherry Hill Eyam  Various tree works at two location on behalf od Monyash Parish Council Fere Mere & Rake End Wood	Accept Accept Accept Accept
P5419  NP/TCA/1023/1186  P  NP/TCA/1023/1189  P11305  NP/TCA/1023/1190  P10849  NP/TCA/1023/1191  P1886  NP/TCA/1023/1192  P4204C  NP/TCA/1023/1193 P7057  NP/TCA/1023/1194 P	T3 - Elm - Crown lift to the line. Cherry Tree Farm Baslow & Bubnell  Photographs of Group 9 (screen grabs from surveyor video), Group 8 (screen grabs from surveyor video) and Tree 865. Location map.Castleton Tree Safety Survey Tables. non provided Castleton  Shown in the photographs are two sycamores I am requesting to remove one is a smaller damaged one on the boundary. The larger one is completely taking over the garden and is now too big for its location and proximity to the house. Shown in the photograph you can see that the trunk splits into co-dominant leaders but with a very tight union which will potentially be a weak point in the future. Due to its proximity to the property this will have terrible consequences if it were to fail. Rock House Monyash  Shown in the photographs are a number of self set sycamores that have been let to grow by the current tenants. As you can see they are growing directly out of the base of the wall of the shed and are in fact now starting to damage it. For this reason I request that they be removed. Grove Cottage  Wetton  T1 - Hornbeam -Reduce ( as previously done), due to obstructing the street lamp, overhanging the footpath and causing problems to the drain. T2 - Golden Conifer - Dismantle due to the close proximity to the garage' Replanting with 3 Rowans. Bridge End Close Ashford  T1 & T2 - Copper Beech & Redwood - Crown lift T3 - Cedar - Dismantle as poor condition suppressed specimen T4 - Oak - Crown lift ( the line) T5 - Ash - Dismantle as suffering from die back Coombs Hay Bakewell  T1 - Ash - Dismantle due to die back and close proximity to the highway. Cherry Hill Eyam  Various tree works at two location on behalf od Monyash Parish Council Fere Mere & Rake End Wood Monyash  Beech x2 (T1 & T2) Crown tift to give 3 m ground clearance Bubnell View Baslow & Bubnell  T1 Sycamore. 15% crown thin to include a crown raise to 4m over the garden	Accept Accept Accept Accept Accept
P5419  NP/TCA/1023/1186  P  NP/TCA/1023/1189  P11305  NP/TCA/1023/1190  P10849  NP/TCA/1023/1191  P1886  NP/TCA/1023/1192  P4204C  NP/TCA/1023/1193 P7057  NP/TCA/1023/1194 P  NP/TCA/1023/1204  P5635  NP/TCA/1023/1214 P1638	T3 - Elm - Crown lift to the line. Cherry Tree Farm Baslow & Bubnell  Photographs of Group 9 (screen grabs from surveyor video), Group 8 (screen grabs from surveyor video) and Tree 865. Location map.Castleton Tree Safety Survey Tables. non provided Castleton  Shown in the photographs are two sycamores I am requesting to remove one is a smaller damaged one on the boundary. The larger one is completely taking over the garden and is now too big for its location and proximity to the house. Shown in the photograph you can see that the trunk splits into co-dominant leaders but with a very tight union which will potentially be a weak point in the future. Due to its proximity to the property this will have terrible consequences if it were to fail. Rock House Monyash  Shown in the photographs are a number of self set sycamores that have been let to grow by the current tenants. As you can see they are growing directly out of the base of the wall of the shed and are in fact now starting to damage it. For this reason I request that they be removed.  Grove Cottage  Wetton  T1 - Hornbeam -Reduce ( as previously done), due to obstructing the street lamp, overhanging the footpath and causing problems to the drain. T2 - Golden Conifer - Dismantle due to the close proximity to the garage' Replanting with 3 Rowans. Bridge End Close Ashford  T1 & T2 - Copper Beech & Redwood - Crown lift T3 - Cedar - Dismantle as poor condition suppressed specimen T4 - Oak - Crown lift (to the line) T5 - Ash - Dismantle as suffering from die back Coombs Hay Bakewell  T1 - Ash - Dismantle as suffering from die back Coombs Hay Bakewell  T1 - Ash - Dismantle due to die back and close proximity to the highway. Cherry Hill Eyam  Various tree works at two location on behalf od Monyash Parish Council Fere Mere & Rake End Wood Monyash  Various tree works at two location on behalf od Monyash Parish Council Fere Mere & Rake End Wood Monyash  Beech x2 (T1 & T2) Crown thin by 20% to gain more light Remove deadwood Crown lift to give 3m ground clearance Bubnell	Accept Accept Accept Accept Accept Accept
P5419  NP/TCA/1023/1186  P  NP/TCA/1023/1189  P11305  NP/TCA/1023/1190  P10849  NP/TCA/1023/1191  P1886  NP/TCA/1023/1192  P4204C  NP/TCA/1023/1193 P7057  NP/TCA/1023/1194 P  NP/TCA/1023/11204  P5635  NP/TCA/1023/1214	T3 - Elm - Crown lift to the line. Cherry Tree Farm Baslow & Bubnell  Photographs of Group 9 (screen grabs from surveyor video), Group 8 (screen grabs from surveyor video) and Tree 865. Location map.Castleton Tree Safety Survey Tables. non provided Castleton  Shown in the photographs are two sycamores I am requesting to remove one is a smaller damaged one on the boundary. The larger one is completely taking over the garden and is now too big for its location and proximity to the house. Shown in the photograph you can see that the trunk splits into co-dominant leaders but with a very tight union which will potentially be a weak point in the future. Due to its proximity to the property this will have terrible consequences if it were to fail. Rock House Monyash  Shown in the photographs are a number of self set sycamores that have been let to grow by the current tenants. As you can see they are growing directly out of the base of the wall of the shed and are in fact now starting to damage it. For this reason I request that they be removed. Grove Cottage  Wetton  T1 - Hornbeam -Reduce ( as previously done), due to obstructing the street lamp, overhanging the footpath and causing problems to the drain. T2 - Golden Conifer - Dismantle due to the close proximity to the garage' Replanting with 3 Rowans. Bridge End Close Ashford  T1 & T2 - Copper Beech & Redwood - Crown lift T3 - Cedar - Dismantle as suffering from die back Coombs Hay Bakewell  T1 - Ash - Dismantle due to die back and close proximity to the highway. Cherry Hill Eyam  Various tree works at two location on behalf od Monyash Parish Council Fere Mere & Rake End Wood Monyash  Beech x2 (T1 & T2) Crown thin by 20% to gain more light Remove deadwood Crown lift to give 3m ground clearance Bubnell View Baslow & Bubnell  T1 Sycamore. 15% crown thin to include a crown raise to 4m over the garden and lateral reduction only by 2m over the house. Al Abri	Accept Accept Accept Accept Accept Accept
P5419  NP/TCA/1023/1186  P  NP/TCA/1023/1189  P11305  NP/TCA/1023/1190  P10849  NP/TCA/1023/1191  P1886  NP/TCA/1023/1192  P4204C  NP/TCA/1023/1193 P7057  NP/TCA/1023/1194 P  NP/TCA/1023/1204  P5635  NP/TCA/1023/1214 P1638  NP/TCA/1023/1217	T3 - Elm - Crown lift to the line. Cherry Tree Farm Baslow & Bubnell  Photographs of Group 9 (screen grabs from surveyor video), Group 8 (screen grabs from surveyor video) and Tree 865. Location map.Castleton Tree Safety Survey Tables. non provided Castleton  Shown in the photographs are two sycamores I am requesting to remove one is a smaller damaged one on the boundary. The larger one is completely taking over the garden and is now too big for its location and proximity to the house. Shown in the photograph you can see that the trunk splits into co-dominant leaders but with a very tight union which will potentially be a weak point in the future. Due to its proximity to the property this will have terrible consequences if it were to fail. Rock House Monyash  Shown in the photographs are a number of self set sycamores that have been let to grow by the current tenants. As you can see they are growing directly out of the base of the wall of the shed and are in fact now starting to damage it. For this reason I request that they be removed. Grove Cottage  Wetton  T1 - Hornbeam -Reduce ( as previously done), due to obstructing the street lamp, overhanging the footpath and causing problems to the drain. T2 - Golden Conifer - Dismantle due to the close proximity to the garage' Replanting with 3 Rowans. Bridge End Close Ashford  T1 & T2 - Copper Beech & Redwood - Crown lift T3 - Cedar - Dismantle as poor condition suppressed specimen T4 - Oak - Crown lift (to the line) T5 - Ash - Dismantle as suffering from die back Coombs Hay Bakewell  T1 - Ash - Dismantle due to die back and close proximity to the highway. Cherry Hill Eyam  Various tree works at two location on behalf od Monyash Parish Council Fere Mere & Rake End Wood Monyash Beech x2 (T1 & T2) Crown thin by 20% to gain more light Remove deadwood Crown lift to give 3m ground clearance Bubnell View Baslow & Bubnell  T1 Sycamore, 15% crown thin to include a crown raise to 4m over the garden and lateral reduction only by 2 m over the house. Al Abri Waterhouses	Accept Accept Accept Accept Accept Accept Accept
P5419  NP/TCA/1023/1186  P  NP/TCA/1023/1189  P11305  NP/TCA/1023/1190  P10849  NP/TCA/1023/1191  P1886  NP/TCA/1023/1192  P4204C  NP/TCA/1023/1193 P7057  NP/TCA/1023/1194 P  NP/TCA/1023/11204  P5635  NP/TCA/1023/1217 P4196 + 11072	T3 - Elm - Crown lift to the line. Cherry Tree Farm Baslow & Bubnell  Photographs of Group 9 (screen grabs from surveyor video), Group 8 (screen grabs from surveyor video) and Tree 865. Location map.Castleton Tree Safety Survey Tables.  Shown in the photographs are two sycamores I am requesting to remove one is a smaller damaged one on the boundary. The larger one is completely taking over the garden and is now too big for its location and proximity to the house. Shown in the photograph you can see that the trunk splits into co-dominant leaders but with a very tight union which will potentially be a weak point in the future. Due to its proximity to the property this will have terrible consequences if it were to fall. Rock House Monyash  Shown in the photographs are a number of self set sycamores that have been let to grow by the current tenants. As you can see they are growing directly out of the base of the wall of the shed and are in fact now starting to damage it. For this reason I request that they be removed. Grove Cottage  Wetton  T1 - Hombeam -Reduce ( as previously done), due to obstructing the street lamp, overhanging the footpath and causing problems to the drain. T2 - Golden Conifer - Dismantle due to the close proximity to the garage' Replanting with 3 Rowans. Bridge End Close Ashford  T1 & T2 - Copper Beech & Redwood - Crown lift T3 - Cedar - Dismantle as poor condition suppressed specimen T4 - Oak - Crown lift (be line) T5 - Ash - Dismantle as suffering from die back Coombs Hay Bakewell  T1 - Ash - Dismantle due to die back and close proximity to the highway. Cherry Hill Eyam  Various tree works at two location on behalf od Monyash Parish Council Fere Mere & Rake End Wood Monyash  Seech x2 (T1 & T2) Crown thin by 20% to gain more light Remove deadwood Crown lift to give 3m ground clearance Bubnell View Baslow & Bubnell  T1 Sycamore. 15% crown thin to include a crown raise to 4m over the garden and lateral reduction only by 2m over the house. Al Abri Waterhouses	Accept Accept Accept Accept Accept Accept Accept
P5419  NP/TCA/1023/1186  P  NP/TCA/1023/1189  P11305  NP/TCA/1023/1190  P10849  NP/TCA/1023/1191  P1886  NP/TCA/1023/1192  P4204C  NP/TCA/1023/1193 P7057  NP/TCA/1023/1194 P  NP/TCA/1023/1204  P5635  NP/TCA/1023/1217 P4196 + 11072  NP/TCA/1023/1238	T3 - Elm - Crown lift to the line. Cherry Tree Farm Baslow & Bubnell  Photographs of Group 9 (screen grabs from surveyor video), Group 8 (screen grabs from surveyor video) and Tree 865. Location map.Castleton Tree Safety Survey Tables. non provided Castleton  Shown in the photographs are two sycamores I am requesting to remove one is a smaller damaged one on the boundary. The larger one is completely taking over the garden and is now too big for its location and proximity to the house. Shown in the photograph you can see that the runk splits into co-dominant leaders but with a very tight union which will potentially be a weak point in the future. Due to its proximity to the property this will have terrible consequences if it were to fail. Rock House Monyash  Shown in the photographs are a number of self set sycamores that have been let to grow by the current tenants. As you can see they are growing directly out of the base of the wall of the shed and are in fact now starting to damage it. For this reason I request that they be removed. Grove Cottage  Wetton  T1 - Hornbeam -Reduce ( as previously done), due to obstructing the street lamp, overhanging the footpath and causing problems to the drain. T2 - Golden Conifer - Dismantle due to the close proximity to the garage' Replanting with 3 Rowans. Bridge End Close Ashford  T1 & T2 - Copper Beech & Redwood - Crown lift T3 - Cedar - Dismantle as poor condition suppressed specimen T4 - Qak - Crown lift (to the line) T3 - Ash - Dismantle as suffering from die back Coombs Hay Bakewell  T1 - Ash - Dismantle as bus location on behalf od Monyash Parish Council Fere Mere & Rake End Wood Monyash  Beech x2 (T1 & T2) Crown thin by 20% to gain more light Remove deadwood Crown lift to give 3m ground clearance Bubnell View Baslow & Bubnell  T1 Sycamore - 15% crown thin to include a crown raise to 4m over the garden and lateral reduction only by 2m over the house.  Al Abri Waterhouses  See attached tree survey - Grove House Litton tree works schedule 5-10-23 LPA.Xis Grove House L	Accept Accept Accept Accept Accept Accept Accept
P5419  NP/TCA/1023/1186  P  NP/TCA/1023/1189  P11305  NP/TCA/1023/1190  P10849  NP/TCA/1023/1191  P1886  NP/TCA/1023/1192  P4204C  NP/TCA/1023/1193 P7057  NP/TCA/1023/1194 P  NP/TCA/1023/11204  P5635  NP/TCA/1023/1217 P4196 + 11072  NP/TCA/1023/1238  P5770  NP/TCA/1023/1238	T3. EIM - Crown lift to the line. Cherry Tree Farm Baslow & Bubnell  Photographs of Group 9 (screen grabs from surveyor video), Group 8 (screen grabs from surveyor video) and Tree 865. Location map. Castleton Tree Safety Survey Tables.  Photographs are two sycamores I am requesting to remove one is a smaller damaged one on the boundary. The larger one is completely taking over the garden and is now too big for its location and proximity to the house. Shown in the photograph you can see that the trusk splits into co-dominant leaders but with a very tight union which will potentially be a weak point in the future. Due to its proximity to the property this will have terrible consequences of it were to fail.  Rock House Monyash  Shown in the photographs are a number of self set sycamores that have been let to grow by the current tenants. As you can see that be runk split and the self-base of the wall of the shed and are in fact now starting to damage it. For this reason I request that they be removed.  Grove Cottage  Wetton  T1 - Hornbeam-Reduce (as previously done), due to obstructing the street lamp, overhanging the footpath and causing problems to the drain.  T2 - Golden Conifer - Dismantle due to the close proximity to the garage' Replanting with 3 Rowans.  Bridge End Close  Astlord  T1 & T2 - Copper Beach & Redwood - Crown lift  T3 - Ocdar - Dismantle as poor condition suppressed specimen  T4 - Oak - Crown lift (to the line)  T5 - Ash - Dismantle as poor condition suppressed specimen  T4 - Oak - Torawn lift (to the line)  T5 - Ash - Dismantle as usfering from die back  Coomba Hay  Bakevell  T1 - Ars - Dismantle due to die back and close proximity to the highway.  Cherry Hill  Eyam  Various tree works at two location on behalf od Monyash Parish Council  Fere Mere & Rake End Wood  Monyash  Morry and provided tree survey - Grove House Litton tree works schedule 5-10-23  LPA xis  Grove House  Litton  1. Sycamore - Acer pseudoplatanus - fell  2. Nower pin in decline: fell  CMAK - Horse Chestnut in decline: fell  CM	Accept Accept Accept Accept Accept Accept Accept Accept
P5419  NP/TCA/1023/1186  P  NP/TCA/1023/1189  P11305  NP/TCA/1023/1190  P10849  NP/TCA/1023/1191  P1886  NP/TCA/1023/1192  P4204C  NP/TCA/1023/1193 P7057  NP/TCA/1023/1194 P  NP/TCA/1023/1204  P5635  NP/TCA/1023/1217 P4196 + 11072  NP/TCA/1023/1238  P5770  NP/TCA/1023/1238	T3 - EIm - Crown lift to the line. Cherry Tree Farm Basiow & Bubnell  Photographs of Group 9 (screen grabs from surveyor video), Group 8 (screen grabs from surveyor video) and Tree 865. Location map. Castleton Tree Safety Survey Tables.  In provided Castleton  Shown in the photographs are two sycamores I am requesting to remove one is a smaller damaged one on the boundary. The larger one is completely taking or the state of the promitive of the boundary. Shown in grant and significant of the state of the promitive of the boundary. Shown in the photographs are two by do the boundary. The larger one is completely taking or the state of	Accept Accept Accept Accept Accept Accept Accept Accept Accept
P5419  NP/TCA/1023/1186  P  NP/TCA/1023/1189  P11305  NP/TCA/1023/1190  P10849  NP/TCA/1023/1191  P1886  NP/TCA/1023/1192  P4204C  NP/TCA/1023/1193 P7057  NP/TCA/1023/1194 P  NP/TCA/1023/1204  P5635  NP/TCA/1023/1217 P4196 + 11072  NP/TCA/1023/1238  P5770  NP/TCA/1023/1238	T3 - Elm - Crown lift to the line. Cherry Tree Farm Baslow & Bubnell  Photographs of Group 9 (screen grabs from surveyor video), Group 8 (screen grabs from surveyor video) and Tree 965. Location map Castleton Tree Safety Survey Tables.  non provided Castleton  Shown in the photographs are two sycamores I am requesting to remove one is a smaller damaged one on the boundary. The larger one is completely taking over the garden and is now too big for its location and proximity to the house. Shown in the photograph you can see that the trunk splits indo co-dominant leaders but with a very tight union which will potentially be a weak point in the future. Due to its proximity to the property this will have terrible consequences if it were to fail.  Rock House Monyash  Shown in the photographs are a number of self set sycamores that have been let to grow by the current tenants. As you can see they are growing directly out of the base of the wall of the shed and are in fact now starting to damage it. For this reason I request that they be removed.  Grove Cottage  Wetton  T1- Hombeam -Reduce ( as previously done), due to obstructing the street lamp, overhanging the footpath and causing problems to the drain.  T2- Golden Confer - Dismantle due to the close proximity to the garage' Replanting with 3 Rowans.  Bridge End Close Ashford  T1 & T2 - Copper Beech & Redwood - Crown lift T3 - Codedar - Dismantle as poor condition suppressed specimen  T4 - Oak - Crown lift (to the lime) T3 - Ash - Dismantle as suffering from die back Combat Hay Bakewell  T1 - Ash - Dismantle as suffering from die back Combat Hay Bakewell  T1 - Ash - Dismantle due to die back and close proximity to the highway. Cherry Hill Eyam  Various tree works at two location on behalf od Monyash Parish Council Fare Mere & Rake End Wood Monyash Backwell Just Backwell  T1 - Ash - Dismantle due to die back and close proximity to the highway. Crown lift to by 20% to gain more light Remove deadwood Crown lift to give Am ground clearance Buhnell View Baslow & Buhnell	Accept Accept Accept Accept Accept Accept Accept Accept Accept
P5419  NP/TCA/1023/1186  P  NP/TCA/1023/1189  P11305  NP/TCA/1023/1190  P10849  NP/TCA/1023/1191  P1886  NP/TCA/1023/1192  P4204C  NP/TCA/1023/1193 P7057  NP/TCA/1023/1194 P  NP/TCA/1023/1204  P5635  NP/TCA/1023/1214 P1638  NP/TCA/1023/1217 P4196 + 11072  NP/TCA/1023/1238  P5770  NP/TCA/1023/1238  P5770  NP/TCA/1023/1247 P2741  NP/TCA/1023/1249  P3687	T3 - EIM - Crown lift to the line. Cherry Tree Farm Baslow & Bubnell  Photographs of Group 9 (screen grabs from surveyor video), Group 8 (screen grabs from surveyor video) and Tree 865. Location map. Castleton Tree Safety Survey Tables.  In provided Castleton  Shown in the photographs are two sycamores I am requesting to remove one is a smaller damaged one on the boundary. The larger one is completely taking over the garden and is now too big for its location and proximity to the house. Shown in the photograph you can see that the trunk splits into co-dominant leaders but with a very light union which will potentially be a west point in the future. Due to its proximity to the property this will have terrible consequences if it were to fail.  Rock House Monyash  Shown in the photographs are a number of self set sycamores that have been let to grow by the current tenants. As you can see they are growing directly out of the base of the wall of the shad and are in fact now starting to damage it. For this reason I request that they be removed.  Growe Cottage  Wetton  T1 - Hornbeam -Reduce ( as previously done), due to obstructing the street lamp, overhanging the footpath and causing problems to the drain.  T2 - Colden Conifer - Dismantle due to the close proximity to the garage Replanting with 3 Rowans.  Bridge End Clorifer - Dismantle due to the close proximity to the garage Replanting with 3 Rowans.  Bridge End Clorifer.  T3 - Cotage Dismantle as sport condition suppressed specimen  T4 - Cak - Crown lift (to the line)  T5 - Ash - Dismantle as suffering from die back  Combs Hay  Bakewell  T1 - Ast - Dismantle as two location on behalf of Monyash Parish Council Fere Mere & Rake End Wood Monyash  Mornantle Street of the Street S	Accept
P5419  NP/TCA/1023/1186  P  NP/TCA/1023/1189  P11305  NP/TCA/1023/1190  P10849  NP/TCA/1023/1191  P1886  NP/TCA/1023/1192  P4204C  NP/TCA/1023/1193 P7057  NP/TCA/1023/1194 P  NP/TCA/1023/1204  P5635  NP/TCA/1023/1214 P1638  NP/TCA/1023/1217 P4196 + 11072  NP/TCA/1023/1238  P5770  NP/TCA/1023/1238  P5770  NP/TCA/1023/1247 P2741  NP/TCA/1023/1249  P3687  NP/TCA/1023/1249	T3-Em. Crown if to the line. Charry Tree Farm Baslov & Bubnel Photographs of Group 9 (screen grabs from surveyor video). Group 8 (screen grabs from surveyor video) and Tree 865. Location map. Castleton Tree Safety Survey Tables. On provided Castleton Shown in the photographs are two sycanores. I am requesting to remove one is a smaller damaged one on the boundary. The larger one is compilately taking over the garden and is now too big for its location and proximity to the house. Shown in the photography ouc anse than the trunk split into co-dominant leaders but with a very tight union which will potentially be a weak point in the future. Due to its proximity to the property this will have terrible consequences if it were to fail. Rock House Monyash Shown in the photographs are a number of self set sycamores that have been let to grow by the current tenants. As you can see they are growing directly out of the base of the vall of the shed and are in fact now starting to damage it. For this reason I request that they be removed. Grove Cottage Wetcon  T1- Hombeam-Reduce ( as previously done), due to obstructing the street lamp, overhanging the footpath and causing problems to the drain. T2- Golden Coroller - Dismantle due to the close proximity to the garage' Replating with 3 Rowans. Bridge Emd Coroller - Dismantle due to the close proximity to the parage' Replating with 3 Rowans. Bridge Emd Coroller - Dismantle due to the back and close proximity to the highway. Cherry Hill Eyam  T1- Ash - Dismantle as suffering from die back Coombs Hay Balakwell  T1- Ash - Dismantle as two location on behalf of Monyash Parish Council Fere Mere & Rake End Wood Monyash  T1- Sycamore. 15% crown thin to include a crown raise to 4m over the garden and lateral reduction only by 2m over the house.  Al Abri Waterhouses  See attached free survey - Grove House Litton tree works schedule 5-10-23 LPA. xis Grove House Litton  T1- Sycamore - Acer pseudoplatanus - fell 2. Norwegiam Maple - Acer platanoidos - fell 3. Lime - Tilla cordinate - fel	Accept
P5419  NP/TCA/1023/1186  P  NP/TCA/1023/1189  P11305  NP/TCA/1023/1190  P10849  NP/TCA/1023/1191  P1886  NP/TCA/1023/1192  P4204C  NP/TCA/1023/1193 P7057  NP/TCA/1023/1194 P  NP/TCA/1023/1204  P5635  NP/TCA/1023/1214 P1638  NP/TCA/1023/1217 P4196 + 11072  NP/TCA/1023/1238  P5770  NP/TCA/1023/1247  P2741  NP/TCA/1023/1249  P3687  NP/TCA/1023/1249	T3-Em Crown if to the line. Charry Tree Farm Baslow & Bubnell  Photographs of Group 9 (screen grabs from surveyor video), Group 8 (screen grabs from surveyor video) and Tree 865. Location map. Castleton Tree Safety Survey Tables.  Shown in the photographs are two sycanores I am requesting to remove one is carefully survey. Tables are survey or the survey of the sycanores I am requesting to remove one is owned the grade and is now too big for its location and proximity to the house. Shown in the photograph you can see that the true was plis into co-dominant leaders but with a very tight union which will potentially be a weak point in the future. Due to its proximity to the property this will have terrible consequences if it were to fall.  Rock House Monyash  Shown in the photographs are a number of self set sycanores that have been let up grow by the current tenants. As you can see they are growing directly out of the base of the wall of the shed and are in fact now starting to damage it. For this reason I request that they be removed.  Grove Cottage  Wetton  T1- Hombeam -Reduce ( as previously done), due to obstructing the street lamp, overhanging the footpath and causing problems to the drain.  T2- Golden Confer - Dismantle due to the close proximity to the garage' Replating with 3 Rowans.  Bridge End Close Ashford  T1- X - Copper Beach & Redwood - Crown lift.  T3- Cedera - Dismantle as poor condition suppressed specimen.  T4- Osk - Crown lift (to the line).  T3- Ash - Dismantle as for condition suppressed specimen.  T4- Osk - Crown lift (to the line).  T3- Ash - Dismantle as uffering from die back  Comba thay galance and self-read from the back and close proximity to the highway.  Charry Hill  Eyam  Vanous tree works at two location on behalf of Monyash Parish Council Fere Mere & Rake End Wood  Monyash  See attached tree survey - Grove House Litton tree works schedule 5-10-23 LPA xis  Grove House  Litton - Will and the self-read fall  G4L + Horse Chestmut dead: fell  G8D + Horse Chestmut dead: fell  G8D +	Accept
P5419  NP/TCA/1023/1186  P  NP/TCA/1023/1189  P11305  NP/TCA/1023/1190  P10849  NP/TCA/1023/1191  P1886  NP/TCA/1023/1192  P4204C  NP/TCA/1023/1193 P7057  NP/TCA/1023/1194 P  NP/TCA/1023/1204  P5635  NP/TCA/1023/1217 P4196 + 11072  NP/TCA/1023/1238  P5770  NP/TCA/1023/1238  P5770  NP/TCA/1023/1247  P2741  NP/TCA/1023/1249  P3687  NP/TCA/1023/1249  P3687  NP/TCA/1023/1250  P11325  NP/TCA/1023/1251	T3 - Em Crown if to the line. Cherry Tree Film - Crown film to the line. Cherry Tree Film - Crown film to the line. Cherry Tree Film - Crown film to the line. Cherry Tree Film - Crown	Accept
P5419  NP/TCA/1023/1186  P  NP/TCA/1023/1189  P11305  NP/TCA/1023/1190  P10849  NP/TCA/1023/1191  P1886  NP/TCA/1023/1192  P4204C  NP/TCA/1023/1193 P7057  NP/TCA/1023/1194 P  NP/TCA/1023/1204  P5635  NP/TCA/1023/1214 P1638  NP/TCA/1023/1217 P4196 + 11072  NP/TCA/1023/1238  P5770  NP/TCA/1023/1238  P5770  NP/TCA/1023/1249  P3687  NP/TCA/1023/1249  P3687  NP/TCA/1023/1250  P11325  NP/TCA/1023/1251	T3-Em - Crown if to the line. Cherry Tree Farm Baslov & Bubnell  Photographs of Group 9 (screen grabs from surveyor video), Group 8 (screen grabs from surveyor video) and Tree 855. Location map. Castleton Tree Safety Survey Tables.  In the photographs are two sycamores I am requesting to remove one is a smaller damaged one on the boundary. The larger one is completely taking over the garden and is now too big for its location and proximity to the house. Shown in the photograph you can see that the trunk agils into co-dominant leaders but with a very tight union which will potentially be a weak point in the future. Due to its proximity to the property this will have terrible consequences if it were to fall.  Place of the see that the trunk agils into co-dominant leaders but with a very tight union which will potentially be a weak point in the future. Due to its proximity to the property this will have terrible consequences if it were to fall.  Place Albouse Morryath  Shown in the photographs are a number of self set sycamores that have been let its grow by the current terraints. As you can see they are growing directly out of the base of the wall of the shed and are in fact row starting to damage it. For Location Carlow Cottage Wetton  T1. Horntheam -Reduce (as previously done), due to obstructing the street lamp, overhanging the footpath and causing problems to the drain.  T2. Golden Cerolier - Dismantle due to the close proximity to the agrage' Registrating with 3 Rowans.  Bridge End Close Ashford  T1. & T2. Copper Beech & Redwood - Crown Ilft.  T3. Cectur Dismantle as suffering from die back  Comba Hay.  Various tree works at two location on behalf of Monyash Parish Council Fern Mere & Rake End Wood Monyash  Various tree works at two location on behalf of Monyash Parish Council Fern Mere & Rake End Wood Monyash  Various tree works at two location on behalf of Monyash Parish Council Fern Mere & Rake End Wood Monyash  Various tree works at two location on behalf of Monyash Parish Council Fern Mere & Rake End	Accept
P5419  NP/TCA/1023/1186  P  NP/TCA/1023/1189  P11305  NP/TCA/1023/1190  P10849  NP/TCA/1023/1191  P1886  NP/TCA/1023/1192  P4204C  NP/TCA/1023/1193 P7057  NP/TCA/1023/1194 P  NP/TCA/1023/1204  P5635  NP/TCA/1023/1214 P1638  NP/TCA/1023/1217 P4196 + 11072  NP/TCA/1023/1238  P5770  NP/TCA/1023/1238  P5770  NP/TCA/1023/1247 P2741  NP/TCA/1023/1249  P3687  NP/TCA/1023/1249  P3687  NP/TCA/1023/1250  P11325  NP/TCA/1023/1251  P5464  NP/TCA/1023/1252 P10240  NP/TCA/1023/1252	T3 - Em - Crown lift to the line. Cherry Tree Farm Basion & Bubrell Photographs of Gooup 9 (screen grabs from surveyor video), Group 8 (screen grabs from surveyor video) and Tree 865. Location map. Casteton Tree Safety Survey Tables. non provided Casteton  Shown in the photographs are two sycamores I am requesting to remove one is a smaller damaged one on the boundary. The larger one is completely laking over the garden and is now too big for its location and proximity to the house. Shown in the photographs varies the first the time stage too determinant factors. The larger one is completely laking over the garden and is now too big for its location and proximity to the house. Shown in the photographs are a number of self set sycamores that have been lot to grow the self-self-self-self-self-self-self-self-	Accept
P5419  NP/TCA/1023/1186  P  NP/TCA/1023/1189  P11305  NP/TCA/1023/1190  P10849  NP/TCA/1023/1191  P1886  NP/TCA/1023/1192  P4204C  NP/TCA/1023/1193 P7057  NP/TCA/1023/1194 P  NP/TCA/1023/1204  P5635  NP/TCA/1023/1217 P4196 + 11072  NP/TCA/1023/1217 P4196 + 11072  NP/TCA/1023/1238  P5770  NP/TCA/1023/1247  P2741  NP/TCA/1023/1249  P3687  NP/TCA/1023/1249  P3687  NP/TCA/1023/1250  P11325  NP/TCA/1023/1251  P5464  NP/TCA/1023/1252 P10240  NP/TCA/1023/1252 P10240  NP/TCA/1023/1271 P11104	T3 - Enr - Crown lift to the line. Cherry Tree Fam. Basiow & Bubnell Photographs of Corup 9 (screen grabs from surveyor video), Group 8 (screen grabs from surveyor video), and Tree 886; Location map. Casteton Tree Safety Survey Tables. Protection of the Corup of Safety Survey Tables. Castedon Castedon Castedon Castedon Castedon Cheven in the photographs are two sycamores I am sequesting to remove one is a seraller danaged one on the boundary. The larger one is completely taking over the garden and is now too big for its location and promisity to the house. Shown in the photographs are a number of self set sycamores that have been focus. Shown in the photographs are a number of self set sycamores that have been focus. Shown in the photographs are a number of self set sycamores that have been focus by the current tomans. As you can see they are growing directly out of the base of the wall of the shed and are in fact now starting to damage 8. For this reason I request that they be removed. Giove Cottage Vietna T1 - Hornbeam-Reduce ( as previously done), due to obstructing the street lump, overhanding the footgan and causing proclaims to the dana. T1 - Hornbeam-Reduce ( as previously done), due to obstructing the street lump, overhanding the footgan and causing proclaims in the dana. T1 - Hornbeam-Reduce ( as previously done), due to obstructing the street lump, overhanding the footgan and causing proclaims and the dana. T1 - Hornbeam-Reduce ( as previously done), due to obstructing the street lump, overhanding the footgan and causing proclaims in the dana. T1 - Hornbeam-Reduce ( as previously done), due to obstructing the street lump, overhanding the footgan and causing proclaims to the dana. T1 - Hornbeam-Reduce ( as previously done), due to obstructing the street lump, overhanding the footgan and causing proclaims to the dana. T1 - Table T2 - Copper Beech & Reduced - Crown lift T3 - Coder - Dismantile due to die back and close proximity to the highway. Chemy Hardberg to the footgan and the danage of the footgan	Accept
P5419  NP/TCA/1023/1186  P  NP/TCA/1023/1189  P11305  NP/TCA/1023/1190  P10849  NP/TCA/1023/1191  P1886  NP/TCA/1023/1192  P4204C  NP/TCA/1023/1193 P7057  NP/TCA/1023/1194 P  NP/TCA/1023/1204  P5635  NP/TCA/1023/1214 P1638  NP/TCA/1023/1217 P4196 + 11072  NP/TCA/1023/1238  P5770  NP/TCA/1023/1247  P2741  NP/TCA/1023/1249  P3687  NP/TCA/1023/1249  P3687  NP/TCA/1023/1250  P11325  NP/TCA/1023/1251  P5464  NP/TCA/1023/1252 P10240  NP/TCA/1023/1252 P10240  NP/TCA/1023/1272 P492  NP/TCA/1023/1272	T3 - Em - Crown lift to the line. Cherry Tree Fam. Basino & Bubnett Photographs of Corup 9 (screen grabs form surveyor video), Group & (screen grabs from surveyor video) and Tree 865. Location map, Casteloto Tree Safety Shorey Tables. Casteloton  Shown in the photographs are two sycamores I am requesting to remove one is a smaller damaged one on the boundary. The larger one is completely taking over the garden and is now too big for its boatch and promiting to the house. Shown in the photograph you can see that the truit apits into ox-dominant leaders but with a very give timo which will potentially be a weap point in the large of the state of the will of the state of the date.  T1 - Ath - Cadden Confere. Dearnate due to the dose proximity to the digital of the state of the state of the will be state of the will be state of the state o	Accept
P5419  NP/TCA/1023/1186  P  NP/TCA/1023/1189  P11305  NP/TCA/1023/1190  P10849  NP/TCA/1023/1191  P1886  NP/TCA/1023/1192  P4204C  NP/TCA/1023/1193 P7057  NP/TCA/1023/1194 P  NP/TCA/1023/1204  P5635  NP/TCA/1023/1214 P1638  NP/TCA/1023/1217 P4196 + 11072  NP/TCA/1023/1238  P5770  NP/TCA/1023/1238  P5770  NP/TCA/1023/1247 P2741  NP/TCA/1023/1249  P3687  NP/TCA/1023/1250  P11325  NP/TCA/1023/1251  P5464  NP/TCA/1023/1252 P10240  NP/TCA/1023/1271 P11104  NP/TCA/1023/1272 P492  NP/TCA/1023/1272 P492  NP/TCA/1023/1271 P11104	T3 - Em - Crown litt to the line. Cherry Trop Em - Crown S Bubrell Basino & Bubrell Photographs of Croup 8 (screen grabs from surveyor video), Group 8 (screen grabs from surveyor video) and Tise 865. Location map. Casterion Tree Safety Survey Trailes. Castletion C	Accept

## Applications determined by the Head of Development Control between 01/10/2023 and 31/10/2023

NP/TCA/1023/1290	1 Horse Chestnut - Prune to give 2m clearance from Church roof 2 Yew trees - Cut ivy at base of trees and trim lower growth away from Church to give 1m clearance	Accept
P11274	1 Holly tree - Prune to give 1m clerance from Church St Micheals Church Middleton & Smerrill	
NP/TCA/1023/1301	1no beech tree and 2no willow trees to rear garden of property, - crown lift beech (T19) to provide 4m clearance and remove deadwood, - coppice willow trees (T28 and T29) at approx 0.5m AGL	Accept
P3650	See tree work schedule and site map for full details.  Meadow Hill House  Litton	
NP/TCA/1023/1303	1 x diseased Maple tree located in the rear garden requesting to be dismantled and removed.	Accept
P6191	1 x Weeping Willow tree located in the front garden requesting to be pollarded.  The Stable House  Great Longstone	
NP/TCA/1023/1309	Cedar- One of, complete removal of tree & stump. Tree is too large for location with roots damaging neighbouring walls and drive way. Proposal is to replant a Silver Birch, Mountain Ash or similar.	Accept
P	Croft Farm Elton	
NP/TCA/1023/1310	T1 Repollard Ash tree over buildings. T2 lift sycamore next to it over the pond. G1 fell 2 dead Elms in wooded area adjacent to the building and G2 fell 2 self set Ash trees at the front of the site showing signs off Ash die back.	Accept
P4893	Cambion Works Castleton	
NP/TPO/1023/1175	T1 & T2 - Elms - Dismantle as dead T3 Ash - Dismantle due to suppressing the neighboring trees T4 Elm - Dismantle as dead T5 Elm - Crown lift to the line	Accept
P1212	T6 Elm - Prune away from the building Stoke Hall Grindleford	
NP/TPO/1023/1176	T1, T3, T4 & T5 - Elm - Dismantle as they are dead and/or dying T2 - Ash - Remove the major deadwood.	Accept
P1212	The Coach House Grindleford	
NP/TPO/1023/1279	Large holly tree x 1 situated next to the house. Risk of damaging the house as very close to the roof and guttering now. Concerns over branches breaking off and interfering with the guttering n the roof. 30% reduction proposed to reduce the height and reduce the risk of damage to the house.	Accept
	Ornamental cypress tree x 1 growing in beech hedgerow. Multi-stemmed so concerns over branches breaking off and causing damage. Tree blocking out the light to the beech hedgerow causing parts of it to die off. Propose to remove this tree. No need to replace as beech hedge already established.	
P4565	Blanche Meadow Farm Parwich	